



S & G Caravan Services

24 Steepdown Road

Sompting

West Sussex

BN15 0LJ

01903 762623

Customers Details

Name: Strafford Motorhomes Ltd

Address: 74 Preston Road, Brighton, Sussex, BN1 4QG

Contact Number: 01273 777777 option 4

Email Address: stephen@strafford.co.uk

Motorhome Details

Registration Number: WFODXTTTRDMJ66445 GX22 BXB

Make: ROLLERTEAM

Model: ZEFIRO 690 Automatic

Year: 2021

Date of service: 29/05/2023

Motorhome service
check reports




**Approved
Workshop**



**All work must be carried out in accordance
with the latest AWS Standard Working
Procedures**

**Log on to www.approvedworkshops.co.uk
and complete the Customer Satisfaction
Survey with your chance to win £150!**

Underbody			Pass	Fail	N/A
Corner steadies & folding steps (where applicable) - check operation & lubricate			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Under slung tanks & pipes - check condition and security			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Electrical Systems			Pass	Fail	N/A
Check leisure battery is being charged by engine			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Check leisure battery is being charged by mains charger			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery (if fitted) - CHECK STATE OF HEALTH AND RECORD READINGS(at time of test. Battery may need a full charge)			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery (if fitted) - CHECK STATE OF CHARGE AND RECORD READINGS(at time of test.battery may need a full charge)			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fridge - check operation from 12V			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fridge - check operation of fridge on 230v			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Interior lighting & equipment - check operation & fuse rating			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Awning light - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wiring earths - check for defects on all ELV circuits (Visual)			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LV inlet plug & extension lead - check condition & resistance across connection pins			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Earth bonding - visual inspection			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RCD unit - check operation of RCD test button & operation of MCB's			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
230v sockets - carry out plug polarity test			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Electric awning & step (if fitted) - check condition & operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Check electric hob operation (if fitted)			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check operation of all other 230v appliances, fans & luminaries			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air conditioning (if fitted) - check operation (weather dependant)			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check that any additional items fitted are to the relevant standard			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gas System (Fridge not serviced unless requested)			Pass	Fail	N/A
Regulator & gas hose - check age, performance & security			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Carry out gas leak check			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LPG tank (if fitted) - check security			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Flame failure devices (FFD) - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Appliances, cooker - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Appliances, heater - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Appliances, fridge - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Appliances, water heater - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gas cylinder - check security			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Ensure all gas dispersal vents are clear			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LPG sticker present (if not apply new sticker)			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Water System			Pass	Fail	N/A
Water pump & pressure switch - check operation			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Taps, micro-switch, valves, pipes & tank (if fitted) - check condition & operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Water filter & housing - check for leaks & replace filter if requested by customer	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Waste system - check for leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Water tanks (if fitted) - check security of all water tanks, including under slug	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drain down - winter only (suggest 01/11 - 31/03 weather determined) (unless advised not by the customer)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Toilet - check security, operation of flush pump & lubricate seals	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Check glycol level (if Alde wet heating system fitted)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check glycol strength (if Alde wet heating system fitted) & record readings	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Ventilation	Pass	Fail	N/A
Fixed ventilation - check for obstruction & free flow of air	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Check all fixed ventilation is guarded against vermin ingress	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof lights-check for cracks, operation & free of obstruction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fire & Safety	Pass	Fail	N/A
Smoke alarm (if fitted) - check operation and replace battery	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Carbon monoxide alarm	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
If a fire extinguisher is fitted, check date and security	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
If a fire blanket is fitted - check security of its housing	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Bodywork	Pass	Fail	N/A
Doors & windows - check operation of all locks, catches, stays & seals	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof - check condition of roof lights & seals & also general condition of roof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Body attachments - check security (including ladders, cycle racks, aerials, satellite dishes, etc.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cab seat - check operation (swivel type or bed configuration only)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Floor - check for sponginess/delamination	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Furniture - check condition & operation of all furniture doors, handles & fixings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Blinds & fly screens - check tension, operation & material for damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rising roof - check operation where applicable	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Damp test - carry out & note readings on a separate damp report sheet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Technician Name: Shaun McHale 			

AWS Tourer Damp Report

Damp survey carried out with non-intrusive damp meter.

Guidance Notes


Readings between 0-15% - readings not recorded because no cause for concern.

Readings between 15%-20% - require further investigation. Compare with the average reading. Consider asking to recheck the area in three months.

Readings above 20% - will identify areas possibly needing remedial work. There may be signs of water ingress or evidence of moisture. Again, it may be worth considering recheck after three months.

Readings above 30% - structural damage may be occurring and deterioration is

Nearside



ALL OK

Offside



ALL OK

N/S



ALL OK

O/S O/S




ALL OK

N/S

Rear

Front


O/S



ALL OK

Roof N/S

O/S



ALL OK

Floor N/S

COMMENTS AND RECOMMENDATIONS

ALL DAMP READINGS ARE BELOW 15% WHEN MARKED ALL OK

Technician Name: Shaun McHale

Date of Report: 29/05/2023

Please note - we would emphasise that the above report accurately reflects the condition of your tourer at the date stated. These reading may be subject to atmospheric conditions, and the company cannot accept any liability for water ingress, which may become apparent at a future date.

Tourer Annual Service Finalisation and Observation Report

Service Information/Additional Work & Observations

Gas Turned Off	<input checked="" type="checkbox"/>	Lights Turned Off	<input checked="" type="checkbox"/>	Exterior Lockers Locked	<input checked="" type="checkbox"/>
Roof Lights Latched	<input checked="" type="checkbox"/>	Water Pump Turned Off	<input checked="" type="checkbox"/>	Exterior Door Locked	<input checked="" type="checkbox"/>
Windows Locked	<input checked="" type="checkbox"/>	Main Power Switch Turned Off	<input checked="" type="checkbox"/>	All Protective Coverings Removed	<input checked="" type="checkbox"/>
All Cupboards Closed/Latched	<input checked="" type="checkbox"/>	Old Parts in Tourer (If Suitable)	<input type="checkbox"/>	Service Book Stamped	<input type="checkbox"/>

Important - Please note:

- 1. The habitation service does not include servicing of the base vehicle and road legal requirements.**
- 2. Appliances are checked for operation only, additional servicing may be required for warranty purposes.**

This service report only relates to the condition of the above tourer at the time of completion of service.
It should not be regarded as evidence of the condition of the items at any other time.

Important - Appliances are checked for operation only, additional servicing may be required for warranty purposes.

Service Technician Name:



Date Service Completed: